

AUTOMOBILE SCANNER - REPORT

DATE: Tuesday, July 09, 2019 09:27 PM

Opel Calibra 1995 (S)

2.0 [X20XEV] - Simtec 56.1

Module Info:

Alpha Code	JG
OPEL Part Number	90508119
Supplier Hardware Number	2514d
Supplier Software Number	00006d
Supplier Software Number	02

Trouble Codes:

73	Unknown Error	Not Present
38	Unknown Error	Not Present

Live Parameters Data:

1	Engine Speed	832	RPM
2	Spark Angle before TDC	6	°CA
3	Battery Voltage	13.4	V
4	Injection Pulse	2.7	ms
5	Mass Air Flow Sensor	0.42	V
6	Mass Air Flow Sensor	11.3	kg/h
7	Coolant Temperature	1.4	V
8	Coolant Temperature	78	°C
9	Intake Air Temperature	1.7	V
10	Intake Air Temperature	27	°C
11	TPS Signal	0.59	V
12	O2 Sensor	4472	mV
13	O2S Integrator	110	steps
14	O2S BLM Partial Load	77	steps
15	O2S BLM Idle	133	steps
16	Idle Air Control	141	steps
17	IAC Integrator	122	steps
18	IAC Adaptation Slope	38	steps
19	Cyl.1 Knock Retard	0	°CA
20	Cyl.2 Knock Retard	0	°CA
21	Cyl.3 Knock Retard	0	°CA
22	Cyl.4 Knock Retard	0	°CA
23	Fuel Tank Ventilation Valve	0	%
24	EGR Pulse Ratio	0	%
25	Desired Engine Idle Speed	816	RPM
26	Fuel Pump Relay	Active	
27	O2 Sensor Loop	Closed	
28	Air/Fuel Ratio	Rich	
29	Sim. Idle Position Switch	Active	
30	Sim. Part Position Switch	Inactive	
31	Sim. Full Position Switch	Inactive	
32	Knock Control	Disabled	
33	A/C Information Switch	Inactive	
34	A/C Compressor Switch	Inactive	
35	A/C Relay	Inactive	
36	Park/Neutral Switch	P-N	

AUTOMOBILE SCANNER - REPORT

DATE: Tuesday, July 09, 2019 09:27 PM

37	Transmission Coding	AT
38	Torque Control	Inactive
39	Secondary Air Pump Relay	Inactive
40	Engine Speed Limit	Inactive
41	Check Light	Off
42	Immobiliser	Active
43	Immobiliser Signal	Received